

Ironing instructions

DIGITAL OFFSET TRANSFER

Application	on cotton	on polyester
Temperature	170 - 180 °C, preheating not required	130 - 140 °C, preheating not required
Time	8 - 10 seconds	20 - 25 seconds
Pressure	Approx. 3.5 bar (average pressure)	
Durability	Approximately 6 months in sealed plastic packaging, at average room temperature, in a dry environment and dark storage.	

ATTENTION! Remove the carrier paper when cold!
Only iron finished garments inside out!



Washable up to 60 °C (delicate cycle) on cotton



Washable up to 40 °C on polyester



Iron inside out



Do not bleach



Do not tumble dry



Do not dry clean