

Ironing instructions

SUBLISTOP TRANSFER

Application	Suitable for cotton, blended fabrics, synthetics, and color-intensive polyester textiles
Temperature	130 °C, preheating not required
Time	25 - 30 seconds
Pressure	0.5 - 0.8 kp/cm ² , 3 - 4 bar (high pressure)
Durability	Approximately 6 months in sealed plastic packaging, at average room temperature, in a dry environment and dark storage.

ATTENTION! Remove the carrier paper when cold!
Only iron decorated garments inside out!



Washable up to 60 °C (delicate cycle)



Iron inside out



Do not bleach



Do not tumble dry



Do not dry clean