

## Ironing instructions

## SCREEN PRINTING TRANSFER

Application Suitable for cotton, cotton blends, natural fibers

Temperature 150 °C, preheating not required

Time 15 seconds

 $0.5 - 0.8 \text{ kp/cm}^2$ , 3 - 4 bar (high pressure)Pressure

Durability Approximately 6 months in sealed plastic packaging. at average room temperature, in a dry environment

and dark storage.

Remove the carrier film when hot (approx. 1-2 seconds after opening the ironing press)! Only iron finished garments on the reverse side!



Washable up to 40 °C



Iron on the left side



Do not bleach



Do not tumble dry



Do not dry clean